

BHI- 00239 REV: 01

OU: 200-UP-1

TSD: N/A ERA: N/A

APPROVAL PAGE

Title of Document:

Site Specific Health & Safety Plan,

200-UP-1 Groundwater Treatability Test

Author(s):

C. H. St. John

Concurrence:

R. J. Fabre'

200 Area Projects Field Support Services Lead

J. Fana 12/29/94
Date

C. D. Wittreich 200-UP-1 Task Lead

M. N. Renter

Projects Industrial Safety Manager

Approval: H. J. G. Zoghbi

200 Area Projects Manager

The approval signatures on this page indicate that this document has been authorized for information release to the public through appropriate channels. No other forms or signatures are required to document this information release.

In some cases, for documents in process or previously issued with a WHC document number before July 1, 1994, this page will appear in documents identified with WHC document numbers. No other forms are required for these documents.

> 12/30/9 BHI-DIS Amc

SITI	E SPECIFIC HEALTH AND SAFETY PLAN	REV. 01	Expires 12/1/95
Project Name/Description/Requested By: 200-UP-1 Groundwater Treatab	ility Test. F. W. Gustason, Test	Engineer	
This Safety Plan covers field activities associated with the pilot-s West Area. The process involves pumping groundwater from W Filters installed upstream of the resin columns remove particulate treated water to meet optimal process flow requirements.	ell #299-W19-23 or alternate(s) through ion-excl	hange resin columns and then re	eturned to the aquifer.
NOTE: Changes made to this safety plan must be documented or	n a Field Change Authorization Form (attached)	and have the approval of the Si	te Safety Officer.
Location: 100	Facility Name/Number: 200-UP-1 Groundwater Tr	reatability Test Site	
FRA RIFS Characterization RCRA Scoping Study Reconnaisance Spill Response Site Description/History/Disposal Fractices: The 200-UP-1 Groundwater Treatement Site is located in the sounce (tent) provides weather protection for the process skie water. Past operation of U-Plant resulted in the discharge of low-level wastes eventually migrated to the aquifer underlying U-Plant and	Soil Gas Sampling Remediation GW Sample utheast quadrant of the intersection of Beloit Ave I and other project equipment. Two 20,000 gallor	on tanks provide temporary stor	age of influent and effluent
	Page <u>1</u> of <u>10</u>		

SITE SPECIFIC HEALTH AND SAFETY PLAN KEY PERSONNEL TRAINING REQUIREMENTS					
Job Title and/or Name	Training Requirements	Misc. Information			
Project Operations/Support Personnel	A, C, D, F, I, L, S and Q				
Project Test Lead (FTL)	A, C, D, E, F, I, L, S and Q				
Project Safety Rep. (SSO)	A, C, D, E, F, I, L, and Q	⁽¹⁾ Maintenance persons performing work			
Maintenance Personnel ⁽¹⁾	A, C, D, F, I, L, and Q	not associated with breached process			
Radiation Control Technicians (RCT)	A, C, D, F, I, L, and Q	system and where there is no potential			
Visitors ⁽²⁾	Q and R	for chemical or radiological exposure;			
Industrial Hygiene Technicians	A, C, D, F, I, L and Q	eg, electricians working on electrical			
	NOTE: Rad. Worker Training (I or II) and bioassay, whole body/chest count	panels, need only meet "visitor"			
	requirements are per controlling RWP.	requirements.			
	Visitors shall comply with all	(2)Visitors are persons not directly			
	instructions/directions from the Fit.	associated with project operations and			
		have no need to enter RCA(s), are not			
age.		associated with breached system			
18 P		activities, and have no foreseeable			
		potential for chemical or radiological			
		exposure. Otherwise, visitors shall			
		meet project operations requirements.			
List the letter(s) of training requirem	ents (classes) required for individuals(s)	named above.			
A. 40 hr Haz. Waste G B. 24 hr Haz. Waste H C. Rad. Worker Training 1 or II I D. 3 Day OJT J E. 8 Hr. Supervisor K F. 8 Hr. Refresher	. First Aid/CPR O. Chest Count . Noise Control P. Asbestos Wo	t U.			

SITE SPECIFIC HEALTH AND SAFETY PLAN WASTE TYPES, WASTE CHARACTERISTICS, AND HAZARD CONCERNS						
Waste Types: Liquid	Solid (Gas Unknown	Other Specify:			
Waste Characteristics:	Chemical Corrosive Toxic Inert	☐ Biological ☐ Flammable ☐ Volatile ☐ Reactive	Radioactive (see RWP No. <u>D-187, 171 & 222)</u> Unknown Other <i>specify</i> :			
Hazards of Concern:	Temperature Extremes Fire Hazards Off Road Vehicle Use Remote Work Area Hazard Communications Pinch Points Overhead Hazards	Noise Electrical Lifting Sanitation Permits Heavy Equipment Walking/Working Surfaces	Biological Compressed Air			
ÖVERALL HAZARD CLASSIFICATI	- :0N:	Medium 🛭 Low	Negligible Unknown			
JUSTIFICATION:						
Fully characterized, low level radiological groundwater contaminants and completely enclosed process system represent a low order of exposure potential during routine operations. Activities such as resin and filter change-out have a higher order of exposure risk but risks are controled by RWPs D-187 Rev. 1, D-125 and D-222. NOTE: ANY EMPLOYEE WHO FINDS A CONDITION/ACTIVITY THAT THEY BELIEVE TO BE UNSAFE SHALL IMMEDIATELY REPORT IT TO THE SSO OR TASK LEAD. IF SUCH CONDITION/ACTIVITY POSES AN IMMINENT HAZARD, THE EMPLOYEE HAS AUTHORITY TO STOP WORK.						
THANK LEMB. IT SUCH COMMITTERS TOOLS AN INTEREST MALAND, THE EMBOVED AND MALANDA TO THE SECOND STATE OF TH						

SITE SPECIFIC HEALTH AND SAFETY PLAN

KNOWN CONTAMINANTS

KNOWN CONTAMINANTS	PEL/TLV (ppm or mg/m³)	IDLH (ppm or mg/m³)	WARNING PROPERTIES/CONCENTRATION (ppm or mg/m³)	1. TARGET ORGANS 2. EXPOSURE SYMPTOMS	IMMEDIATE FIRST AID MEASURES
Technetium90	9x10 ° μCi/ml	N/A	N/A	1. BO 2. N/A	Decon per RCT direction
Uranium ^{rost}	0.2mg/m³ (air) 5×10 ¹¹ μCi/ml	N/A	N/A	1. K 2. N/A	Decon per RCT direction
Carbon Tetrachloride (CCl ₄)	5 ppm	300 ррш	(A) Ether like odor/70 80 ppm	1. L, K, CNS, LS 2. D, HA, CD	FA,MA
i g.≜d.					
er Transfer					

	TARGET ORGANS	EXPOSURE SYMPTOMS	1ST AID MEASURES
NA = Not Available	L = Liver	D = Dizziness	IrW = Irrigate with (H ₂ O)
# NA = Not Available U = Unknown	K = Kidney	I = Skin/Eye/Respiratory Irritant	FA = Get to Fresh Air
NE = Non Established	LS = Lungs	C = Confusion	MA = Medical Aid
N/A = Not Applicable	E – Eyes	F = Fatigue	IS= Wash Soap and Water
WARNING PROPERTIES	S/A = Skin Absorption	II = Headache	
A = Odor	CNS = Central Nervous System	CD = CNS Depression	į
B = Visual	R = Respiratory System	N = Nausea	į
C = Irritant	BO = Bone	W = Weakness	į
	H = Hemopoietic (Blood)	V = Vomiting	
1	O = O(he)	O Other	
1			

SITE SPECIFIC HEALTH AND SAFETY PLAN CHECK LIST					
TEMPERATURE EXTREMES N/A	HEAVY EQUIPMENT/MACHINERY N/A	REMOTE WORK AREA N/A			
Monitor work periodically. Adjust work/rest regimen according to WGT. Minimize/maximize clothing where possible. Drink cool/warm liquids as appropriate. Discuss signs/symptoms of heat/cold stress. NOTE:Temperature extremes are related to seasonal climatic changes. Any introduced temperature extremes require SSO evaluation and approval	Safety features/devices in place and functioning Warning signs in place where required. Flagger assigned where necessary. Proper rigging used. Guards in place. Swing radius roped off or guarded. Regular inspections of equipment	Know your location. Communication available - phone/radio First aid kit and trained personnel Know emergency numbers. Use buddy system when required by manager.			
PERMITS N/A	OVERHEAD HAZARDS N/A	HAZARD COMMUNICATION N/A			
Confined Space Permit. Hot Work Permit. Fall Protection Work Plan. X Radiation Work Permit. Excavation Permit. NOTE: Assure that all necessary permits are obtained prior to initiation of work	Secure loose overhead objects Do not go under suspended load Use tag lines to control loads Wear hardhat Post/barricade overhead hazard areals) as appropriate Brief workers/visitors on overhead work activities	MSDS file in place and current. Containers labeled. Workers apprised of new chemical hazards.			
PINCH POINTS N/A	ELECTRICAL N/A	NOISE N/A			
Assure guards in place Brief site personner on recardor, or pisterior per in points, identify or post areas where guarding is not appropriate or teasible.	GFCt in outdoor/wet locations. Grounding of equipment, Loels and cords in good condition. Cords protected, Exposed wiring guarded or covered	Hearing protection worn. Signs posted. Hearing conservation training			
MALKING/WORKING SUBFACET N/A	SANITATION N/A	LIFTING			
Carry out daily housekeeping efforts. ু keep walkways/work areas clear. ু-bes multi-walkways routes where appropriate (Thag or post problem areas where necessary. অসম	Portable toilets on site or within vehicle reach. Potable water/cups. Wash water and soap Eating/smoking in designated areas only. Empty trash and waste food receptacles daily.	Use proper lifting techniques Use buddy system for awkward/heavy toads. Use mechanical lifting devices as appropriate			
COMPRESSED AIR N/A	FIRE HAZARDS N/A	BIOLOGICAL N/A			
Verify that system pressure is equal to ambient pressure prior to breaching system. Regulate pressure to lowest pressure peeded to perform task. Do not use compressed air for cleaning dusty surfaces.	Flammable liquids stored properly. Combustible materials accumulation. Heaters approved type/installed properly. Fire extinguisher in place/proper type. Ignition sources eliminated or protected.	Control rodent intrusion and harborage Be cognizant of poisonous reptiles and insect harborages (cool, dark spaces and equipment that has laid on the ground overnight.)			
	<u></u>	ì			

SITE SPECIFIC HEALTH AND SAFETY PLAN

MONITORING STRATEGY/ACTION LEVELS

EQUIPMENT OR INSTRUMENT	FREQUENCY OF USE	ACTION LEVEL	SPECIFIC ACTION(S)
E	5	85 dBA (8-ltr. TWA)	Determine hearing protection requirements. Post high noise areas
G	6	Per controling RWP	See RWPs D-187 Rev.1, D-125, D-222
G	3 (when system is breached)	Per controling RWP	See RWPs D-187 Rev.1, D-125, D-222
C, M	5 (only if propane/diesel heaters are used)	19.5% O ₂ , 25 ppm CO (8-hr. TWA)	Ventilate space, do not allow entry until monitoring demonstrates safe atmosphere.
ing.			

Where appropriate list the letter or number corresponding to the instrument or monitoring frequency in spaces above.

13					
1	A. PID	H.	Radiation Surveys see RWP No. D-187 Rev. 1, D-171, D-222	1.	Hourly
i	B. FID	1.	Monitoring Not Required	2.	15 Min
(C. CGI/LEL 0.	J	Personal Exposure Monitoring	3.	Continu
1	D. Detector Tubes	K.	Biological Monitoring	4.	AM/PN
1	E. Sound Level Meter	L.	Halide Detectors	5.	As dete
۱,	F. Odyssey	Μ.	CO Meter	6.	As dete
	G. Rad Survey instrument(s)	N.		7.	
	,			8.	
ll					

- in.
- nuous
- termined by SSO
- termined by RCT/RWP

SITE SPECIFIC SAFETY HEALTH AND SAFETY PLAN PERSONAL PROTECTIVE EQUIPMENT

Job Task	Work Zone/Location	PPE Level	
Routine Process Operations (10),(12), (7 at/in conex boxes)		Level "D"HardHat, Substantial footware, safety glasses	
Filter/resin Change-out (8),(12),RMSA & RBA		As determined by controling RWP/RCT	
Maintenance activities	(10) (12)	(10)Level "D", (12)As per RCT/RWP	
Sampling (10),(12)		(10)IEVEL "D", (12)As per RCT/RWP	
		Note: Additional PPE may be needed for specific tasks/activities as per SSO/RCT or FTL	
in pertinent information. Take out item 1. Sampling 7.	Support Zone 13.	Level "D" Blue Coveralls Hard Hat Anti C'S per RWP (See Chemical Gloves Hearing Protection Eye Protection above) Steel Toed Shoes Surgical Gloves Splash Protection	
 Decontamination Observation 	contamination 9. Exclusion Zone 15. servation 10. Control Zone 16.	Level "C" APR with cartridge plus level "D" above	
6. Drilling 12		Level "B" Airline respirator Chemical resistant coveralls	

SITE SPECIFIC SAFETY HEALTH AND SAFETY PLAN SITE ACCESS AND WORK ZONES				
1. Support Zone				
Is the area outside of roped boundry which includes conex boxes, Lunch/office trailers and portal	able toilet			
2. Contamination Reduction Zone				
N/A				
3. Exclusion Zone		i		
Temporary or permanent RCA(s)/SCA(s) and RBA(s) as determined by RCT/RWP for specific lo	locations and/or activities			
4. Control Zone				
Inside of roped boundry				
5.	•			
OLIME ALL D				
SITE MAP				
(See Figure-Lattached)				
· 连接				

SITE SPECIFIC HEALTH AND SAFETY PLAN DECONTAMINATION PROCEDURES

Personnel Decontamination	Sampling Equipment Decontamination	Heavy Equipment Decontamination
Generally, no personal decon is required for routine activities. Rad decon may be needed for tools and other equipment as determined by RCT survey. A portable shower (in tent) is available for personnel decon. No eating, smoking or drinking inside of Control Zone boundry.	Equipment decon requirements to be by RCT survey	N/A
i		

EQUIPMENT REQUIREMENTS CHECKLIST (Underline required items or add others)

- -	1.	CONTRACTOR	6.	Signs *	11. HEPA Vacuum	16
	2	<u>PPE</u> (see page #?)	7.	Decon Equipment	12. Supplemental Lighting	17.
	3.	Fire Extinguisher(s)	8.	Radio/Phone	13. Spill containment/cleanup	
	4.	Wind Indicator	9.	Breathing Air	14.	
	5	Eye Wash	10.	Signal Device	15.	


^{*} Control Zone, Authorized Personnel Only, No Smoking, Emergency Shut Off, Parking Area, and other informational/directional signs as deemed appropreiate by SSO/FTL or RCT

Note: Additional equipment may be needed for specific, non-routine tasks as determined by SSO/FTL/RCT

SITE SPECIFIC HEALTH AND SAFETY PLAN EMERGENCY PROCEDURES/CONTACTS

CONTINGENCY PLANS	EMERGENCY CONTACTS NAME	<u>PHONE</u>
FIRE: 1. Alert others to evacuate; 2. Notify Fire Dept. (373-3800) on cell phone 911 on landline phone or by station radio. 3. Try to isolate or contain incipient fires without putting personnel at risk. 4. Direct Fire Dept. to fire.	All Emergencies: Patrol Operations Center	373-3800
	Health and Safety Officer: M. N. Kenter	(W) 373-9733 (Cell 539-2114) (H) 627-5080
PERSONAL INJURY: (other than minor 1st aid) 1. Alert others in area for assistance. 2. Transport injured to medical aid station or call for emergency responders.	Site Safety Officer: C. H. St.John	(W) 376-5459 (Cell 539-2129) (H) 946-7205
3. Provide necessary assistance to injured; ie, stop arterial bleeding, treat for shock, monitor pulse and respiration. 4. Direct emergency responders to injured.	Fire Department: Battalion Chief North	373-3856 (911)
CHEMICAL EXPOSURE. 1. Alert others for assistance, if needed. 2. Notify SSO or	OU Task Lead: C. D. Writtreich	(W) 376-1862 (H) 967-3540
HSO, 3, Taken necessary action to reduce exposure, 4, Show SSO/HSO location/operation/activity involving exposure.	Patrol: Hanford Patrol East	373-3800 (911)
	IT Industrial Safety: J. C. Ellis	372-9548
	Health Physics: M. A. Wesselman	(W) 376-2084 (H) 943-4184
	S. K. DeMers	(W) 376-3707 (H) 582-5317
SPILL CONTROL PLAN	MEDICAL FACILITIES LOCATION	PHONE
Contacts. The Dept., Hazard Material Team (272-2800/011)	HEHF MEDICAL AID STATION: 2719 WA BIO	lg. 373-2714
Containment Kit Located: Connex Boxes and in tent.	KEDLEC HOSPITAL: Richland	946-4611
Other Equipment: Shovels, plastic tubs/buckets, mops.		
Actions to Take: 1. Alert others in area. 2. Notify HAZMAT Team, as appropriate. 3. Try to contain/stop spill using appropriate PPE and without putting personnel at risk. 4. Show location of spill to HAZMAT Team.	ACTIONS TO TAKE: If unusual symptoms are expressed, reported or noted, call Site Safety Officer or Field Support Service Task Lead (or alternates). If injury or illness is serious, call 373-3800 and give your location. Provide 1st aid as needed.	

Figure-1
200-UP-1 Groundwater Treatability Test Site Map



NOTE: NOT A SCALE DRAWING

SITE SPECIFIC HEALTH AND SAFETY PLAN FIELD CHANGE AUTHORIZATION

Section to be Changed		Page	
Person Requesting Change			
Verbal Authorization by Health & Safety Officer	Date	Time	
Description of Change			
Justification for Change			
			· · · · · · · · · · · · · · · · · · ·
			·
Approved By		Date/11me	
Field Team Brief on Change By Name		Date/Time	